



IN-TANK TECHNOLOGY



(Prices Effective January 2020)

FLO KING BX1200 FACTORY REPAIR SERVICE & PARTS

Prices for CPVC parts (gray in color) and polypropylene (white) are shown below. Those are the most popular materials. Specify CPVC or PP when ordering. Kynar (PVDF) and stainless steel are also used but cost more (contact us for prices). For motor replacement outside of factory, Order Item 3 (Motor/Shaft Assembly) because of difficulty of installing motor alone.

DESCRIPTION	ORDER NO.	PRICE
1. Motor replacement (115 or 230 volt, factory repair only)	1200 MOTOR	\$185.00
2. Reconditioned motor (available only with exchange of reconditionable motor)	1200 MRC	145.00
3. Motor with balanced Teflon-covered shaft attached (includes spacers, motor base screws & Super Slinger; specify voltage)*	1200 MOTSHF ___ (length)* .	250.00
4. Fan cover (includes mounting screws)**	1200 FCOV**	22.00
5. Fan blade (includes mounting screw)**	1200 FBR**	15.00
6. Line cord with switch (factory repair only)	1200 LCS	28.00
7. Spacer replacement (two)—includes mounting screws	1200 SPC	15.00
8. Shaft covered with Teflon heat-shrink tubing*	1200 SHAFT ___ (length)*	70.00
9. Shaft balance and alignment (factory repair only)	1200 BAL	22.00
10. Teflon heat-shrink tubing (covers shaft)	1200 TEF	1.00/inch
11. Pump/motor base† (factory repair only)	1200 PB†	75.00
12. Body replacement† (factory repair only)	1200 BR ___ (length)†	45.00
13. Pump/motor base, body, & impeller housing†	1200 PBBH ___ (length)†	200.00
14. Body and impeller housing† (factory repair only)	1200 BHR ___ (length)†	120.00
15. Impeller housing† (factory repair only; includes upper stage plate)	1200 HR†	80.00
16. Flow plate	1200 FLP	10.00
17. Plug and retap filter screw holes (each, factory repair only)	1200 TAP	7.50
18. Filter screw replacement (each)	1200 FS	3.50
19. Impeller	1200 IMP	55.00
20. Super Slinger	1200 RSS	6.00
21. Drip cover (includes hardware: carriage bolt & nut)	DC4	20.00
22. Drip cover hardware (carriage bolt & nut)	DC4HW	4.00
23. Handle (includes mounting screw)	1200 H	16.00
24. Universal Bracket (1")—includes hardware: screws & washers	UNBK1	25.00
25. Hardware for Universal Bracket (1"), screws & washers	UNBK1HW	3.00
26. Pump/motor base hardware (2 titanium screws, 8-32 x 3/4")	1200 PBHW	5.00
27. Sandblast, strip & clean pump (factory repair only)	1200 SANDSTRIP	35.00
28. Strip and clean pump (factory repair only)	1200 STRIP	25.00

* Pump body length and pump material of construction must be specified when ordering these parts. To determine pump body length, measure "A" dimension on Bulletin 15 or on "BX1200 Specs" page at www.floking.com. Important: Shaft thread size is 1/4" for pumps made of CPVC and stainless steel, and 3/8" for pumps made of polypro and Kynar.

** When ordering Fan Cover or Fan Blade, you must specify motor manufacturer. Rotom, Fasco, McMillan, Connex, A.O. Smith & SYMT motors have been used. Parts are not interchangeable. See "BX1200 Repair Parts" page at www.floking.com.

† For repairs outside of factory, order Item 13 (combination base/body/impeller housing) to avoid machining operations associated with separate purchase of pump/motor base (Item 11), pump body (Item 12), and/or impeller housing (Item 15). Specify pump body length and material of construction when ordering. Prices for CPVC parts (gray in color) and polypropylene (white) are shown above. Kynar (PVDF) and stainless steel are also used but cost more (contact us for prices).