



# IN-TANK TECHNOLOGY



(Prices Effective January 2017)

## FLO KING BX3000 FACTORY REPAIR SERVICE & PARTS

Prices for CPVC parts (gray in color) and polypropylene (white) are shown below. Those are the most popular materials. Specify CPVC or PP when ordering. Kynar (PVDF) and stainless steel are also used but cost more (contact us for prices).

DESCRIPTION	ORDER NO.	PRICE
1. Handle (includes Handle Hardware) . . . . .	<b>3000 H</b> . . . . .	\$40.00
2. Handle hardware (screws & lock washers) . . . . .	<b>3000 HHW</b> . . . . .	3.00
3. Motor (single phase, specify voltage; add \$125 for 3 Phase) . . . . .	<b>3000 MOTOR</b> . . . . .	380.00
4. Reconditioned motor (available only with exchange of reconditionable motor) . . . . .	<b>3000 MRC</b> . . . . .	260.00
5. Motor with balanced Teflon-covered shaft attached* . . . . .	<b>3000 MOTSHF</b> ___ (length)* . . . . .	470.00
6. Motor bearings and seal replacement (factory installation) . . . . .	<b>3000 MB</b> . . . . .	110.00
7. Fan cover (includes mounting screws)** . . . . .	<b>3000 FCOV**</b> . . . . .	30.00
8. Fan blade (includes hardware: screw or clip)** . . . . .	<b>3000 FBR**</b> . . . . .	17.00
9. Fan blade clip (for Leeson motor only)** . . . . .	<b>3000 FBC**</b> . . . . .	3.00
10. Capacitor cover** . . . . .	<b>3000 CAPCOV**</b> . . . . .	25.00
11. Capacitor replacement** . . . . .	<b>3000 CAPR**</b> . . . . .	30.00
12. Line cord installation (includes line cord restraint)** . . . . .	<b>3000 LC**</b> . . . . .	27.00
13. Line cord restraint** . . . . .	<b>3000 LCR**</b> . . . . .	14.00
14. Switch replacement** . . . . .	<b>3000 SWITCH**</b> . . . . .	25.00
15. Switch boot cover** . . . . .	<b>3000 SBC**</b> . . . . .	7.00
16. Switch guard** . . . . .	<b>3000 SGR**</b> . . . . .	10.00
17. Switch box** . . . . .	<b>3000 SB**</b> . . . . .	45.00
18. Switch box cover** . . . . .	<b>3000 SBXC**</b> . . . . .	15.00
19. Switch box hardware** . . . . .	<b>3000 SBHW**</b> . . . . .	3.00
20. Strip and clean pump (factory repair only) . . . . .	<b>3000 STRIP</b> . . . . .	30.00
21. Universal Bracket (3")—includes hardware: screws, washers . . . . .	<b>UNBK3</b> . . . . .	28.00
22. Hardware for Universal Bracket (3"), screws & washers . . . . .	<b>UNBK3HW</b> . . . . .	3.00
23. Shaft covered with Teflon heat-shrink tubing* . . . . .	<b>3000 SHAFT</b> ___ (length)* . . . . .	95.00
24. Boot seal . . . . .	<b>3000 VBS</b> . . . . .	14.00
25. Shaft balance and alignment (factory repair only) . . . . .	<b>3000 BAL</b> . . . . .	25.00
26. Teflon heat-shrink tubing (covers shaft) . . . . .	<b>3000 TEF</b> . . . . .	2.00/inch
27. Spacer for pump/motor base (each, includes screw) . . . . .	<b>3000 SPC</b> . . . . .	3.75
28. Pump/motor base† (factory repair only) . . . . .	<b>3000 PB†</b> . . . . .	85.00
29. Pump/motor base hardware (four 1/4-20 x 1-3/4" screws) . . . . .	<b>3000 PBHW</b> . . . . .	4.50
30. Body replacement† (factory repair only) . . . . .	<b>3000 BR</b> ___ (length)† . . . . .	110.00
30a. Pump/motor base & body† (includes screws) . . . . .	<b>3000 BBR</b> ___ (length)† . . . . .	190.00
31. Impeller (includes Impeller Washer & Super Slinger) . . . . .	<b>3000 IMP</b> . . . . .	75.00
32. Impeller washer . . . . .	<b>3000 TIW</b> . . . . .	6.00
33. Super slinger . . . . .	<b>3000 TSS</b> . . . . .	8.00
34. Swiveling impeller housing (includes Teflon Strap & Screws) . . . . .	<b>3000 SHR</b> . . . . .	140.00
35. Lock screw for swiveling impeller housing . . . . .	<b>3000 SHLS</b> . . . . .	3.00
36. Teflon strap for swiveling impeller housing . . . . .	<b>3000 STRAP</b> . . . . .	10.00
37. Upper stage plate . . . . .	<b>3000 USP</b> . . . . .	20.00
38. Flow plate replacement (old style) . . . . .	<b>3000 FLP</b> . . . . .	Discontinued
39. Filter screw replacement (each) . . . . .	<b>3000 FS</b> . . . . .	3.00
40. Plug and retap filter screw holes (each, factory repair only) . . . . .	<b>3000 TAP</b> . . . . .	7.50

\* Specify pump body length and, where applicable, motor voltage when ordering these parts. To determine pump body length, measure "A" dimension on Bulletin 14 or on "BX3000 Specs" page at [www.floking.com](http://www.floking.com). Add \$125 for 3-phase motor.

\*\* Check motor nameplate to determine if you have a Baldor or Leeson motor when ordering these parts (not interchangeable). Also specify voltage when ordering motor.

† For repairs outside of factory, you must order Item 30a (pump/motor base and body replacement) to avoid machining operations associated with separate purchase of either pump body (Item 30) or pump/motor base (Item 28).