



# IN-TANK TECHNOLOGY



(Prices Effective January 2021)

## FLO KING BX5000 FACTORY REPAIR SERVICE & PARTS

Prices for CPVC parts (gray in color) and polypropylene (white) are shown below. Those are the most popular materials. Specify CPVC or PP when ordering. Kynar (PVDF) and stainless steel are also used but cost more (contact us for prices).

DESCRIPTION	ORDER NO.	PRICE
1. Handle (includes Handle Hardware) . . . . .	<b>5000 H</b> . . . . .	\$40.00
2. Handle hardware (screws & lock washers) . . . . .	<b>5000 HHW</b> . . . . .	3.00
3. Motor (single phase, specify voltage; add \$150 for 3 Phase) . . . . .	<b>5000 MOTOR</b> . . . . .	440.00
4. Reconditioned motor (available only with exchange of reconditionable motor) . . . . .	<b>5000 MRC</b> . . . . .	290.00
5. Motor with balanced Teflon-covered shaft attached* . . . . .	<b>5000 MOTSHF</b> ___ (length)* . . . . .	520.00
6. Motor bearings and seal replacement (factory installation) . . . . .	<b>5000 MB</b> . . . . .	110.00
7. Fan cover (includes mounting screws)** . . . . .	<b>5000 FCOV**</b> . . . . .	32.00
8. Fan blade (includes hardware: screw or clip)** . . . . .	<b>5000 FBR**</b> . . . . .	18.00
9. Fan blade clip (for Leeson motor only)** . . . . .	<b>5000 FBC**</b> . . . . .	4.00
10. Capacitor cover** . . . . .	<b>5000 CAPCOV**</b> . . . . .	27.00
11. Capacitor replacement** . . . . .	<b>5000 CAPR**</b> . . . . .	30.00
12. Line cord installation (includes line cord restraint)** . . . . .	<b>5000 LC**</b> . . . . .	27.00
13. Line cord restraint** . . . . .	<b>5000 LCR**</b> . . . . .	15.00
14. Switch replacement** . . . . .	<b>5000 SWITCH**</b> . . . . .	27.00
15. Switch boot cover** . . . . .	<b>5000 SBC**</b> . . . . .	8.00
16. Switch guard** . . . . .	<b>5000 SGR**</b> . . . . .	11.00
17. Switch box** . . . . .	<b>5000 SB**</b> . . . . .	45.00
18. Switch box cover** . . . . .	<b>5000 SBXC**</b> . . . . .	16.00
19. Switch box hardware** . . . . .	<b>5000 SBHW**</b> . . . . .	3.00
20. Strip and clean pump (factory repair only) . . . . .	<b>5000 STRIP</b> . . . . .	30.00
21. Universal Bracket (3")—includes hardware: screws, washers . . . . .	<b>UNBK3</b> . . . . .	30.00
22. Hardware for Universal Bracket (3"), screws & washers . . . . .	<b>UNBK3HW</b> . . . . .	4.00
23. Shaft covered with Teflon heat-shrink tubing* . . . . .	<b>5000 SHAFT</b> ___ (length)* . . . . .	95.00
24. Boot seal . . . . .	<b>5000 VBS</b> . . . . .	15.00
25. Shaft balance and alignment (factory repair only) . . . . .	<b>5000 BAL</b> . . . . .	30.00
26. Teflon heat-shrink tubing (covers shaft) . . . . .	<b>5000 TEF</b> . . . . .	2.00/inch
27. Spacer for pump/motor base (each, includes screw) . . . . .	<b>5000 SPC</b> . . . . .	4.00
28. Pump/motor base† (factory repair only) . . . . .	<b>5000 PB†</b> . . . . .	90.00
29. Pump/motor base hardware (four 1/4-20 x 1-3/4" screws) . . . . .	<b>5000 PBHW</b> . . . . .	5.00
30. Body replacement† (factory repair only) . . . . .	<b>5000 BR</b> ___ (length)† . . . . .	120.00
30a. Pump/motor base & body replacement† . . . . .	<b>5000 BBR</b> ___ (length)† . . . . .	200.00
31. Impeller (includes Impeller Washer & Super Slinger) . . . . .	<b>5000 IMP</b> . . . . .	80.00
32. Impeller washer . . . . .	<b>5000 TIW</b> . . . . .	6.00
33. Super slinger . . . . .	<b>5000 TSS</b> . . . . .	9.00
34. Swiveling impeller housing (includes Teflon Strap & Screws) . . . . .	<b>5000 SHR</b> . . . . .	150.00
35. Lock screw for swiveling impeller housing . . . . .	<b>5000 SHLS</b> . . . . .	3.50
36. Teflon strap for swiveling impeller housing . . . . .	<b>5000 STRAP</b> . . . . .	10.00
37. Upper stage plate . . . . .	<b>5000 USP</b> . . . . .	25.00
38. Filter screw replacement (each) . . . . .	<b>5000 FS</b> . . . . .	3.50
39. Plug and retap filter screw holes (each, factory repair only) . . . . .	<b>5000 TAP</b> . . . . .	7.50
40. Sandblast, strip & clean pump (factory repair only) . . . . .	<b>5000 SANDSTRIP</b> . . . . .	45.00

\* Specify pump body length and, where applicable, motor voltage when ordering these parts. To determine pump body length, measure "A" dimension on Bulletin 13.9 or on "BX5000 Specs" page at [www.floking.com](http://www.floking.com). Add \$150 for 3-phase motor.

\*\* Check motor nameplate to determine if you have a Baldor or Leeson motor when ordering these parts (not interchangeable). Also specify voltage when ordering motor.

† For repairs outside of factory, you must order Item 30a (pump/motor base and body replacement) to avoid machining operations associated with separate purchase of either pump body (Item 30) or pump/motor base (Item 28).