



IN-TANK TECHNOLOGY



(Prices Effective January 2021)

FLO KING BXL5000 FACTORY REPAIR SERVICE & PARTS

Prices for CPVC parts (gray in color) and polypropylene (white) are shown below. Those are the most popular materials. Specify CPVC or PP when ordering. Kynar (PVDF) and stainless steel are also used but cost more (contact us for prices).

DESCRIPTION	ORDER NO.	PRICE
1. Motor replacement (includes motor pulley, MBHW, fan blade, fan cover) . . .	50XL MOTOR (specify voltage)	\$440.00
2. Reconditioned motor (available only with exchange of reconditionable motor)	50XL MRC	330.00
3. Motor bearing replacement (factory installation)	50XL MB	110.00
4. Fan cover (includes screws; specify Baldor or Leeson motor when ordering)	50XL FCOV	32.00
5. Fan blade (specify Baldor motor with screw or Leeson with clip)	50XL FBR	18.00
6. Fan blade hardware (screw for Baldor or clip for Leeson, as required)	50XL FBHW	4.00
7. Capacitor cover (specify Baldor or Leeson motor)	50XL CAPCOV	27.00
8. Capacitor replacement (specify Baldor or Leeson motor).	50XL CAPR	30.00
9. Line cord installation (includes line cord restraint)	50XL LC	27.00
10. Line cord restraint (specify Baldor or Leeson motor)	50XL LCR	15.00
11. Switch replacement (specify Baldor or Leeson motor)	50XL SWITCH	27.00
12. Switch boot cover (specify Baldor or Leeson motor)	50XL SBC	8.00
13. Switch guard (specify Baldor or Leeson motor)	50XL SGR	11.00
14. Switch box (specify Baldor or Leeson motor)	50XL SB	45.00
15. Switch box cover (specify Baldor or Leeson motor)	50XL SBXC	16.00
16. Switch box hardware (specify Baldor or Leeson motor)	50XL SBHW	3.00
17. Adjustable standoff (factory repair only)	50XL ASO	24.00
18. Strip and clean pump (factory repair only)	50XL STRIP	30.00
19. Boot seal	50XL VBS	15.00
20. Shaft balance and alignment (factory repair only)	50XL BAL	30.00
21. Teflon heat-shrink tubing (covers shaft)	50XL TEF	2.00/inch
22. Spacer for pump base (each, includes mounting screw)	50XL SPC	4.00
23. Teflon-covered shaft with SS shaft pulley & bearings (new style)†	50XL NSHPB ___ (length)*	250.00
24. Motor pulley replacement (SS, new style)†	50XL NPR	60.00
25. Body replacement** (factory repair only)	50XL BR ___ (length)*	110.00
26. Pump base** (factory repair only)	50XL PB	85.00
27. Pump base hardware (four 1/4-20 screws, 1-3/4" long)	50XL PBHW	5.00
28. Pump base & body** (includes Spacers & Screws)	50XL BBR ___ (length)*	190.00
29. Impeller (includes Impeller Washer & Super Slinger)	50XL IMP	85.00
30. Impeller washer	50XL TIW	6.00
31. Super slinger	50XL TSS	9.00
32. Swiveling impeller housing (includes Strap, Filter Screws, Lock Screw) . . .	50XL SHR	150.00
33. Lock screw for swiveling impeller housing	50XL SHLS	3.50
34. Teflon strap for swiveling impeller housing	50XL STRAP	10.00
35. Upper stage plate	50XL USP	25.00
36. Filter screw replacement (each)	50XL FS	3.50
37. Plug and retap filter screw holes (each, factory repair only)	50XL TAP	7.50
38. Motor base assembly with heel (includes belt & hardware)†	50XL MB15	335.00
39. Motor base hardware (hex-head screws, flat washers, lock washers)	50XL MBHW	5.00
40. Belt (new style)†	50XL NB15	50.00
41. Belt replacement (new style, factory installation of belt)	50XL NBR15	60.00
42. Belt drive cover (includes screws and washers)	50XL BDC15	80.00
43. Belt drive cover hardware (screws and washers)	50XL BDCHW15	5.00
44. Pump shaft bearing replacement (factory installation)	50XL PSBR	110.00
45. Rework motor base (factory repair only)	50XL MBR	45.00
46. Heel (includes screws, SS flat washers, inside & outside Heel washers)	50XL MBH	110.00
47. Shaft pulley replacement (SS, new style with keyway)†	50XL NSPR	70.00
48. Heel, Teflon-covered shaft, shaft bearing, belt assembly (new style)†	50XL HSBBA ___ (length)*	400.00
49. Sandblast, strip & clean pump (factory repair only)	50XL SANDSTRIP	45.00

* Specify pump body length when ordering these parts. To determine pump body length, measure "A" dimension on Bulletin 14.2 or on "BXL5000 Specs" page at www.floking.com

** For repairs outside of the Flo King factory, you must order Item 28 (pump base and body replacement) to avoid machining operations associated with separate purchase of either pump body (Item 25) or pump base (Item 26). Specify pump material and body length.

† BXL5000 units purchased prior to Dec. 2002 use aluminum pulleys with "old style" belts. Units manufactured as of Dec. 2002 use stainless-steel pulleys and "new style" belts. BXL2500 units sent to factory will be upgraded to SS pulleys and new-style belt. Because old-style parts are now obsolete, old-style pumps must be upgraded.