



IN-TANK TECHNOLOGY



(Prices Effective January 2023)

FLO KING BX650 FACTORY REPAIR SERVICE & PARTS

Prices for CPVC parts (gray in color) and polypro (white) are shown. Specify CPVC or PP when ordering. Polypro subject to upcharge depending on market price. Kynar (PVDF) and stainless steel are also used but cost more (contact us for prices). For motor replacement outside of factory, Order Item 3 (Motor/Shaft Assembly) because of difficulty of installing motor alone.

DESCRIPTION	ORDER NO.	PRICE
1. Motor replacement (115 or 230 volt, factory repair only)	650 MOTOR	\$210.00
2. Reconditioned motor (available only with exchange of reconditionable motor)	650 MRC	165.00
3. Motor with balanced Teflon-covered shaft attached (includes spacers, motor base screws & Super Slinger; specify voltage)*	650 MOTSHF ___ (length)*	290.00
4. Fan cover (includes mounting screws)**	650 FCOV**	27.00
5. Fan blade (includes mounting screw)**	650 FBR**	18.75
6. Line cord with switch (factory repair only)	650 LCS	34.00
7. Spacer replacement (two)—includes mounting screws	650 SPC	19.00
8. Shaft covered with Teflon heat-shrink tubing*	650 SHAFT ___ (length)*	83.00
9. Shaft balance and alignment (factory repair only)	650 BAL	26.00
10. Teflon heat-shrink tubing (covers shaft)	650 TEF	1.40/inch
11. Pump/motor base† (factory repair only)	650 PB†	88.00
12. Body replacement† (factory repair only)	650 BR ___ (length)†	55.00
13. Pump/motor base, body, & impeller housing†	650 PBBH ___ (length)†	230.00
14. Body and impeller housing† (factory repair only)	650 BHR ___ (length)†	143.00
15. Impeller housing† (factory repair only; includes upper stage plate)	650 HR†	94.00
16. Flow plate	650 FLP	12.00
17. Plug & retap filter screw holes (each, factory repair only)	650 TAP	9.00
18. Filter screw replacement (each)	650 FS	4.50
19. Impeller	650 IMP	63.00
20. Super slinger	650 RSS	7.00
21. Drip cover (includes hardware: carriage bolt & nut)	DC4	24.00
22. Drip cover hardware (carriage bolt & nut)	DC4HW	5.00
23. Handle (includes mounting screw)	650 H	20.00
24. Universal Bracket (1")—includes hardware: screws & washers	UNBK650-1	31.00
25. Hardware for Universal Bracket (1"), screws & washers	UNBK650-1HW	3.75
26. Pump/motor base hardware (2 titanium screws, 8-32 x 3/4")	650 PBHW	6.00
27. Sandblast, strip & clean pump (factory repair only)	650 SANDSTRIP	42.00
28. Strip and clean pump (factory repair only)	650 STRIP	30.00

* Pump body length and pump material of construction must be specified when ordering these parts. To determine pump body length, measure "A" dimension on Bulletin 15.5 or on "BX650 Specs" page at www.floking.com. Important: Shaft thread size is 1/4" for pumps made of CPVC and stainless steel, and 3/8" for pumps made of polypro and Kynar.

** When ordering Fan Cover or Fan Blade, you must specify motor manufacturer. Rotom, Fasco, McMillan, Connex, A.O. Smith & SYMT motors have been used. Parts are not interchangeable. See "BX650 Repair Parts" page at www.floking.com

† For repairs outside of factory, order Item 13 (combination base/body/impeller housing) to avoid machining operations associated with separate purchase of pump/motor base (Item 11), pump body (Item 12), and/or impeller housing (Item 15). Specify pump body length and material of construction when ordering. Prices for CPVC parts (gray in color) and polypropylene (white) are shown above. Kynar (PVDF) and stainless steel are also used but cost more (contact us for prices).